


Ford ~ wdv + coker
Fu.



16 Has had power supply at top of pole disconnected. Could do with removing this light + bracket from pole

light no 28 is currently in-repair break, see it has been given the no 28.

27 Extra column